

This report aims to provide an assessment of a used laptop. The purpose is to evaluate the condition of the device and provide potential buyers with detailed information regarding any cosmetic imperfections.

KEY HIGHLIGHTS

Sy	stem Memory		an 19	-
16	GB	and the second s		1 All
Sto	orage Type		- Mar	
512	2 GB	A. A.	R	CALIFORNET
Sci	reen Sizer			
	4 Inch			
Pro	ocessor			
	el Core i7			
Gai	neration			

GENERAL EVALUTION

The DELL XPS 13 (9310) 2-IN-1 laptop has been carefully inspected to assess its condition accurately, while the device is generally in normal condition we have identified some observations which are detailed below.

EXTERIOR EXAMINATION



The top cover exhibits scratches and the sides of the palmrest has major dent. However there is a scratches on backcove and hinge rubber are missing. Furthermore, the bottom panel remains clean and devoid of any scratches or marks, indicating minimal use or careful maintenance. Overall, the rest of the device's exterior remains in normal condition.

INTERNAL ASSESSMENT

The internal components of the laptop are in excellent condition. The keyboard functions perfectly, with all keys intact and showing no signs of wear. Similarly, the touchpad operates smoothly and is free from any signs of wear or damage. The screen is immaculate, devoid of any scratches, smudges, or blemishes, ensuring a clear and crisp display.

All ports and connectors have been thoroughly inspected and are in optimal working condition, guaranteeing reliable connectivity. The **battery's health 71%** is also robust, maintaining its capacity effectively for prolonged usage.

CONCLUSION

The DELL XPS 13 (9310) 2-IN-1 laptop is in excellent overall condition. Despite these minor imperfections, the device remains fully functional and ready for use.

RECOMENDATIONS

We recommend the DELL XPS 13 (9310) 2-IN-1 laptop for individuals who prioritize performance over minor cosmetic blemishes. With its robust specifications and reliable performance, this laptop offers exceptional value for users needing a powerful computing solution.

DISCLAIMER

This inspection report is based on a comprehensive visual examination conducted by our certified technicians. While every effort has been made to provide an accurate assessment, individual perspectives can vary. Hence prospective buyers are encouraged to conduct their own inspection or request additional information to ensure complete satisfaction with their purchase decision.