


INSPECTION REPORT



103994841182



Fully Functional Battery 85% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Minor Wear

Top Cover Minor wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The Top cover has scratches.
- The keyboard and palm rest are clean.
- The back cover has minor scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.