

INSPECTION REPORT



104182858635



Fully Functional  Battery 84%  3-Month Warranty



COSMETIC SUMMARY

Display  Scratch Free
Keyboard  Clean
Bottom Cover  Minor Wear

Top Cover  Minor wear
Palm Rest  Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits scratches, adhesive residue from removed stickers.
- The keyboard and palm rest are clean.
- The back cover has scratches and sticker mark.

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.