


INSPECTION REPORT



104335876421



Fully Functional Battery 91% 3-Month Warranty



COSMETIC SUMMARY

|              |   |              |           |   |            |
|--------------|---|--------------|-----------|---|------------|
| Display      | ✓ | Scratch Free | Top Cover | ⚠ | Minor wear |
| Keyboard     | ✓ | Clean        | Palm Rest | ✓ | Clean      |
| Bottom Cover | ⚠ | Minor Wear   |           |   |            |

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits no scratches.
- The keyboard and palm rest are clean.
- The back cover is clean.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

**INSPECTION DISCLAIMER**

Cosmetic assessment reflects appearance only and does not impact device performance.