


INSPECTION REPORT



104540895828



Fully Functional Battery 92% 3-Month Warranty



COSMETIC SUMMARY

Display	✓ Scratch Free	Top Cover	⚠ Major wear
Keyboard	✓ Clean	Palm Rest	✓ Clean
Bottom Cover	⚠ Minor Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits major scratch.
- The keyboard and palm rest are clean.
- The back cover is clean.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.