

INSPECTION REPORT



104655906026



Fully Functional Battery 86% 3-Month Warranty



COSMETIC SUMMARY

Display	✓ Scratch Free	Top Cover	⚠ Major wear
Keyboard	✓ Clean	Palm Rest	✓ Clean
Bottom Cover	⚠ Major Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:





TECHNICIAN OBSERVATIONS

- The top cover exhibits major scratches and paint peeling from the corner sides.
- The keyboard and palm rest are clean.
- The back cover also has scratches.

 Genuine Windows

 Charger Included

 Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.