


INSPECTION REPORT



104655906027



Fully Functional  Battery 64%  3-Month Warranty



COSMETIC SUMMARY

Display  Scratch Free
Keyboard  Clean
Bottom Cover  Minor Wear

Top Cover  Major wear
Palm Rest  Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover has minor scratches, and the paint is peeling off from the top corners.
- The keyboard and sides of the palm rest are clean.
- The back cover has minor scratches.

 Genuine Windows

 Charger Included

☒ Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.