

INSPECTION REPORT



104784915523



Fully Functional Battery 72% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Minor Wear

Top Cover Minor wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- Top cover exhibits minor scratches and a dent on the left-side corner..
- The keyboard and palm rest are clean.
- The back cover is clean.

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.