

INSPECTION REPORT



104792918697



Fully Functional Battery 72% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	Minor wear
Keyboard	✓	Clean	Palm Rest	✓ Clean
Bottom Cover		Major Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover has minor scratches.
- The keyboard and the sides of the palm rest are clean.
- Major scratches, on the back cover.



Genuine Windows



Charger Included



Ready to Use



Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.