

INSPECTION REPORT



104792918848



Fully Functional  Battery 81%  3-Month Warranty



COSMETIC SUMMARY

Display  Scratch Free  
Keyboard  Clean  
Bottom Cover  Minor Wear

Top Cover  Major wear  
Palm Rest  Clean

DEVICE CONDITION PHOTOS

Image 1: Top Cover



Image 2: Back Cover



TECHNICIAN OBSERVATIONS

- The top cover has Major scratches.
- The keyboard and the sides of the palm rest are clean.
- Minor scratches on the back cover.

 Genuine Windows     Charger Included     Ready to Use     Professionally Tested

**INSPECTION DISCLAIMER**

Cosmetic assessment reflects appearance only and does not impact device performance.