

# INSPECTION REPORT



|                    |                |
|--------------------|----------------|
| Brand              | Processor      |
| DELL LATITUDE 5330 | INTEL CORE i7  |
| Memory             | OS             |
| 16 GB/512 GB       | Windows 11 Pro |

✓ Fully Functional    Battery 79%    3-Month Warranty

## COSMETIC SUMMARY

|              |                |           |              |
|--------------|----------------|-----------|--------------|
| Display      | ✓ Scratch Free | Top Cover | ⚠ Major wear |
| Keyboard     | ✓ Clean        | Palm Rest | ✓ Clean      |
| Bottom Cover | ⚠ Major Wear   |           |              |

## DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits major scratches.
- The keyboard and palm rest are clean.
- The back cover also has major scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.