

INSPECTION REPORT



104792918868



Fully Functional



Battery 77%



3-Month Warranty



COSMETIC SUMMARY

Display ✓ Scratch Free
Keyboard ✓ Clean
Bottom Cover ⚠ Minor Wear

Top Cover ⚠ Minor wear
Palm Rest ✓ Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The Top cover has scratches, paint peeling from the corner sides, and a dent on the left corner.
- The keyboard and palm rest are clean.
- The back cover is clean.

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.