

INSPECTION REPORT



104792918895



Fully Functional Battery 99% 3-Month Warranty



COSMETIC SUMMARY

|              |                |           |              |
|--------------|----------------|-----------|--------------|
| Display      | ✓ Scratch Free | Top Cover | ⚠ Minor wear |
| Keyboard     | ✓ Clean        | Palm Rest | ✓ Clean      |
| Bottom Cover | ⚠ Minor Wear   |           |              |

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The Top cover exhibits no scratches.
- The keyboard and palm rest are clean.
- The back cover has minor scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

**INSPECTION DISCLAIMER**

Cosmetic assessment reflects appearance only and does not impact device performance.