

INSPECTION REPORT



Fully Functional Battery 62% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free  
Keyboard Clean  
Bottom Cover Minor Wear

Top Cover Minor wear  
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover is clean.
- The keyboard and the sides of the palm rest are clean.
- Minor cosmetic wear, on the back cover.



Genuine Windows



Charger Included



Ready to Use



Professionally Tested

## INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.