

INSPECTION REPORT



Fully Functional Battery 85% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	Minor wear
Keyboard	✓	Clean	Palm Rest	✓ Clean
Bottom Cover		Major Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits minor scratches.
- The keyboard and sides of the palm rest are clean.
- The laptop has major scratches on the back cover, along with minor scratches on the right side.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.