

104792919051



This report aims to provide an assessment of a used laptop. The purpose is to evaluate the condition of the device and provide potential buyers with detailed information regarding any cosmetic imperfections.

## KEY HIGHLIGHTS

A graphic with a dark background and a laptop image on the right. The laptop screen shows a forest scene. On the left, there are five white horizontal lines, each with a label and a specification below it.

- Brand  
**DELL LATITUDE 5400**
- System Memory  
**8 GB**
- Storage Type  
**256 GB SSD**
- Screen Size  
**13.9 Inch**
- Processor  
**Intel Core i5**

## General Assessment

The LATITUDE 5400 laptop has been carefully inspected to assess its condition accurately, while the device is generally in Good condition, we have identified some observations which are detailed below.

## Noted Observations



The top cover has no scratches, and the sides of the palm rest are clean. The bottom panel is free of marks, indicating careful use. Overall, the exterior is in excellent condition.

## BATTERY HEALTH

The **battery's health 87%** is also robust, maintaining its capacity effectively for prolonged usage.

## DISCLAIMER

This inspection report is based on a comprehensive visual examination conducted by our certified technicians. While every effort has been made to provide an accurate assessment, individual perspectives can vary. Hence prospective buyers are encouraged to conduct their own inspection or request additional information to ensure complete satisfaction with their purchase decision.