


INSPECTION REPORT



104792919084



Fully Functional Battery 78% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	⚠	Minor wear
Keyboard	✓	Clean	Palm Rest	✓	Clean
Bottom Cover	⚠	Minor Wear			

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top exhibits no scratches however have scratches on sides.
- The keyboard and palm rest are clean.
- The back cover has minor scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.