

INSPECTION REPORT



104796918541



Fully Functional Battery 92% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Minor Wear

Top Cover Major wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:




Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits major scratches.
- The keyboard and palm rest are clean.
- The back cover has minor scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.