

INSPECTION REPORT



104796918595



Fully Functional Battery 91% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Minor Wear

Top Cover Minor wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits minor scratches.
- The keyboard and palm rest are clean.
- The paint is peeling off from the back cover.

 Genuine Windows

 Charger Included

☒ Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.