


INSPECTION REPORT



104796918623



Fully Functional Battery 98% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	⚠	Minor wear
Keyboard	✓	Clean	Palm Rest	✓	Clean
Bottom Cover	⚠	Minor Wear			

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits no scratches.
- The keyboard is clean however palm rest has yellowish discoloration.
- The back cover has no scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.