

INSPECTION REPORT



104806919344



Fully Functional  Battery 65%  3-Month Warranty



COSMETIC SUMMARY

Display  Scratch Free
Keyboard  Clean
Bottom Cover  Major Wear

Top Cover  Major wear
Palm Rest  Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:





TECHNICIAN OBSERVATIONS

- The top cover exhibits scratches and paint peeling from the corners & sides.
- The keyboard and palm rest are clean.
- The back cover also has scratches.

 Genuine Windows

 Charger Included

 Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.