

INSPECTION REPORT



Fully Functional Battery 60% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	⚠	Minor wear
Keyboard	✓	Clean	Palm Rest	✓	Clean
Bottom Cover	⚠	Minor Wear			

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover has scratches, peeling paint, and a dent on left corner.
- The keyboard and palm rest are clean.
- The paint is peeling off from the back cover.

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.