

INSPECTION REPORT



104806919510



Fully Functional Battery 73% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	Minor wear
Keyboard	✓	Clean	Palm Rest	✓ Clean
Bottom Cover		Minor Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits no scratches however paint is peeling off from the left side, and there is a dent on left side and on LAN port.
- The keyboard and palm rest are clean.
- The back cover is clean.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.