

INSPECTION REPORT



104822920190



Fully Functional Battery 88% 3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover		Minor wear
Keyboard	✓	Clean	Palm Rest	✓	Clean
Bottom Cover		Minor Wear			

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- Top cover exhibits scratches.
- The keyboard and palm rest are clean.
- The back cover has minor scratches.

 Genuine Windows

 Charger Included

 Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.