

INSPECTION REPORT



104822920193



Fully Functional Battery 89% 3-Month Warranty



COSMETIC SUMMARY

Display	✓ Scratch Free	Top Cover	⚠ Minor wear
Keyboard	✓ Clean	Palm Rest	✓ Clean
Bottom Cover	⚠ Minor Wear		

DEVICE CONDITION PHOTOS

Image 1:



- Top cover exhibits scratches.
- The keyboard and palm rest are clean.
- The back cover has minor scratches and sticker marks.



 **Charger Included**

☒ Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.