

INSPECTION REPORT



104822920220



Fully Functional  Battery 73%  3-Month Warranty



COSMETIC SUMMARY

Display  Scratch Free
Keyboard  Clean
Bottom Cover  Minor Wear

Top Cover  Minor wear
Palm Rest  Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits no scratches.
- The keyboard and palm rest are clean.
- The back cover is also clean.

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.