


INSPECTION REPORT



104858921405



Fully Functional Battery 64% 3-Month Warranty



COSMETIC SUMMARY

Display	✓ Scratch Free	Top Cover	⚠ Minor wear
Keyboard	✓ Clean	Palm Rest	✓ Clean
Bottom Cover	⚠ Minor Wear		

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover is clean.
- The keyboard and the sides of the palm rest are clean.
- Minor cosmetic wear, including light scratches on the back cover and paint peeling on the palm rest

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.