


INSPECTION REPORT



104860922144



Fully Functional



Battery 96%



3-Month Warranty



COSMETIC SUMMARY

Display ✓ Scratch Free
Keyboard ✓ Clean
Bottom Cover ⚠ Minor Wear

Top Cover ⚠ Minor wear
Palm Rest ✓ Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits minor scratches.
- The keyboard and palm rest are clean.
- The back cover is clean.

 Genuine Windows

 Charger Included

☒ Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.