

INSPECTION REPORT



104860922294



Fully Functional Battery 90% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Minor Wear

Top Cover Minor wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- Top cover exhibits minor scratches.
- The keyboard and palm rest are clean.
- The back cover is clean.

 Genuine Windows

 Charger Included

☒ Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.