

INSPECTION REPORT



Fully Functional Battery 100% 3-Month Warranty



COSMETIC SUMMARY

Display Scratch Free
Keyboard Clean
Bottom Cover Major Wear

Top Cover Major wear
Palm Rest Clean

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover has major scratches, and the paint is peeling off from the sides & corners.
- The keyboard and sides of the palm rest are clean.
- The back cover has scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.