


INSPECTION REPORT



216707001951



Fully Functional  Battery 71%  3-Month Warranty



COSMETIC SUMMARY

Display	✓	Scratch Free	Top Cover	⚠	Minor wear
Keyboard	✓	Clean	Palm Rest	✓	Clean
Bottom Cover	⚠	Major Wear			

DEVICE CONDITION PHOTOS

Image 1:



Image 2:



TECHNICIAN OBSERVATIONS

- The top cover exhibits minor scratches.
- The keyboard and sides of the palm rest are clean.
- The back cover has major scratches.



Genuine Windows



Charger Included



Ready to Use

Professionally Tested

INSPECTION DISCLAIMER

Cosmetic assessment reflects appearance only and does not impact device performance.